

Our Savior Lutheran Church

Harrisburg, Pennsylvania

5,900 s.f. Addition, and Removed Expansive Fill from the Fellowship Hall that caused Slab Settlement.

